

Standon Culvert Works
Photo record #014 upto 23rd August 2024

Downstream catch pit completed.



Cover reinstated over downstream end.



Fence reinstated and painted to neighbouring property.



Internal view of downstream catch pit



Internal view of culvert from downstream end



Concrete repairs completed to upstream.

