

Standon Culvert Works - Downstream Photo record #007 upto 11th April 2024

Access at downstream end of culvert



Stage 3 completed, view upstream.





Blocked inlet near downstream end (southern side), now cleared.



Work area to downstream end.

