

Standon Culvert Works - Upstream
Photo record #006 upto 8th April 2024

Catch pit pumped out for access



Phase 5 sediment removal in progress.



View upstream following sediment removal.



Material loaded for removal from site.

