

Standon Culvert Works - Upstream
Photo record #004 upto 27th March 2024

Progress clearing out sediment from culvert.



View from upstream entrance to culvert.



5m into culvert from upstream end showing sediment build up.

