

Standon Culvert Works - Upstream
Photo record #003 upto 22nd March 2024



Sediment build up to upstream end prior to commencement.



Pumping out.



Sediment removed from catch pit and into culvert.



View into culvert from upstream end following sediment removal.