

Standon Culvert Works - Downstream
Photo record #002 upto 22nd March 2024



Access via lowered fence panel – remove and replace daily.



After cleaning out sediment, prior to breaking out working space.



Cover removed showing clear culvert base prior to forming working space.



Cover re-instated following forming of working space and excavation and removal of material.